

AD-A105 981

ARMY ENGINEER DISTRICT ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. LAKE KAL-TATRI DAM (MO 31039). MIS--ETC(U)
SEP 78

F/G 13/13

UNCLASSIFIED


NL

1 OF 1
AD A
07 9 81

END
DATA
FILMED
11-81
DTIC

LEVEL

AA105981



Original contains color
plates: All DTIC reproductions
will be in black and
white.

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD A105981	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Lake Kal-Tatri (MO 31039) Ste. Genevieve County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Corps of Engineers, St. Louis District		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) N/A
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING National Dam Safety Program. Lake Kal- Tatri Dam (MO 31039). Mississippi- Kaskaskia-St. Louis Basin, Ste. Genevieve County, Missouri. Phase I Inspection		12. REPORT DATE September 1978
16. DISTRIBUTION Report.		13. NUMBER OF PAGES Approximately 35
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
18. SUPPLEMENTARY NOTES		16. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property..		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

SECRET

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

RIVER AUX VASES BASIN

LAKE KAL-TATRI
STE. GENEVIEVE COUNTY, MISSOURI

MISSOURI INVENTORY NO. 31039

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY: ST. LOUIS DISTRICT CORPS OF ENGINEERS
FOR: GOVERNOR OF MISSOURI

SEPTEMBER 1978

DISTRICT STATEMENT A

Approved for release
Distribution Unlimited

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam	Kal-Tatri
State Located	Missouri
County Located	Ste. Genevieve
Stream	River aux Vases
Date of Inspection	1 September 1978

Lake Kal-Tatri Dam No. Mo. 31039 was inspected using the "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed by the Chief of Engineers, U. S. Army, Washington, D. C., with the help of Federal and state agencies, professional engineering organizations, and private engineers. The resulting guidelines are considered to represent a consensus of the engineering profession.

Based on the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property loss could occur in the event of failure of the dam. Four houses would be subjected to flooding with possible damage and/or destruction and possible loss of life. Kal-Tatri Dam is in the small size classification since it is less than 40 feet high and impounds less than 1,000 acre-feet of water.

Our inspection and evaluation indicate that the spillway of Kal-Tatri does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Kal-Tatri Dam is a small size dam with a high hazard potential required by the guidelines to pass from one-half PMF to the PMF. However, considering the high hazard potential to loss of life (four families) and property downstream of the dam and the fact that the two upstream dams, Butterfly and Rainbow, will pass only 20 percent and 15 percent of the PMF, respectively, the spillway size and/or height of the dam should be able to pass the PMF. It was determined that the spillway will pass 5 percent of the PMF without overtopping the dam. Since the spillway for Kal-Tetri Dam is not capable of passing a minimum of one-half (50 percent) of the PMF without overtopping the dam and causing failure, the spillway is considered seriously inadequate and the dam is accordingly classified as an unsafe, non-emergency structure. Also, our evaluation indicates that the spillway will not pass the 100-year flood; that is, a flood having a 1 percent chance of being equalled or exceeded during any given year.

Accession For	100
TIS CR&I	
CIC TIR	
Inspected	
Inspection	
by	
Distribution/	
by	

A

Other deficiencies visually observed by the inspection team were the need for removal of brush on the dam slopes, and the need for riprap protection at the dam/spillway interface to prevent erosion from high spillway flows. The lack of stability and seepage analyses on record is a deficiency that should be corrected.

It is recommended that the owner take action to correct or control the deficiencies described.

Thomas F. Wolff
THOMAS F. WOLFF
Soils Engineer
St. Louis District
Corps of Engineers

Chien H. Hsieh
CHIEN H. HSIEH
Hydraulic Engineer
St. Louis District
Corps of Engineers

SUBMITTED BY:


Paul R. Uehlein
Chief, Engineering Division

21 Sept 78
Date

APPROVED BY:

Sam E. Miller
Colonel, CE, District Engineer

21 Sept 78
Date



Overview of Butterfly Lake, Rainbow
Lake and Kal-Tatri Lake

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
KAL-TATRI DAM - ID NO. 31039

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	4
2.2	Construction	4
2.3	Operation	4
2.4	Evaluation	4
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	5
3.2	Evaluation	6
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	7
4.2	Maintenance of Dam	7
4.3	Maintenance of Operating Facilities	7
4.4	Description of Any Warning System in Effect	7
4.5	Evaluation	7
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	8
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	11
7.2	Remedial Measures	11
APPENDIX		
A	Hydrologic and Hydraulic Analysis Methodology	

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Vicinity Topography
2	X-Section
3	Profile

LIST OF PHOTOGRAPHS

<u>Photograph No.</u>	<u>Title</u>
1	Kal-Tatri Dam - Upstream Face
2	Kal-Tatri Dam - Downstream Bridge and Culverts
3	Kal-Tatri Dam - Spillway and Outlet Channel
4	Kal-Tatri Dam - Downstream Bridge and Culverts
5	Kal-Tatri Dam - Downstream Slope
6	Kal-Tatri Dam - Spillway
7	Kal-Tatri Dam - Spillway

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
LAKE KAL-TATRI DAM - ID NO. 31039

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of the Lake Kal-Tatri Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances. Lake Kal-Tatri is an earth dam which provides a recreation lake for the owner and others living around the lake. Kal-Tatri is the downstream-most lake of a series of three lakes (Butterfly Lake and Rainbow Lake). Butterfly and Rainbow Lakes are owned by the River Bluffs Girl Scout Council, Glen Carbon, Illinois, and were not part of this inspection. They were inspected and reported separately from Lake Kal-Tatri because of different owners. Lake Kal-Tatri has a spillway consisting of a concrete weir with a vertical approach wall. The notched weir is located on top of the concrete wall at the right abutment.

b. Location. Section 27, Township 36 North, Range 7 East.

c. Size Classification. Small.

d. Hazard Classification. High

e. Ownership. Mr. John Kalicak, R. R. 3, Box 190, Farmington, Missouri 63640.

f. Purpose of Dam. Recreation - Resort Area.

g. Design and Construction History. The dam was built in 1966 by Mr. Kalicak, a contractor and the owner of the lake. No preconstruction design information or detailed construction data are known to exist.

h. Normal Operating Procedure. No operating records exist. Water passes over an ungated spillway.

1.3 PERTINENT DATA

a. Combined Drainage and Lake Surface Area.

.09 square miles
2.81 square miles (In tandem upstream dams)

b. Discharge at Damsite.

(1) Estimated ungated emergency spillway capacity at maximum pool elevation.

331 cfs

(2) Estimated experienced maximum flood at damsite - Unknown.

c. Elevation (Feet Above M.S.L.).

(1) Top of dam (minimum elevation of earth embankment) - 745.2.

(2) Spillway crest - 742.9.

(3) Maximum Tailwater - Unknown.

(4) Streambed at Centerline of Dam - estimated - 722.

d. Reservoir. Length of maximum pool - 800 feet.

e. Storage (Acre-feet). Top of Dam Estimated - 77.

f. Reservoir Surface (Acres).

(1) Top of dam - 11 acres.

(2) Spillway crest - 10 acres.

g. Spillway. The length of the weir is 26 feet.

h. Dam.

Type - earthfill.

Length - 800 feet.

Height - 26 feet.

Top width - 15 feet.

Side Slopes - 1 V on 2.5 H.

Zoning - unknown.

Impervious Core - unknown.

Cutoff - unknown.

Grout curtain - none, per Mr. Kalicak.

i. Outlet Works. None.

i. Emergency Spillway. See Section 5.1c(3) for a description of the spillway.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

No design drawings or data are known to exist for the construction of Kal-Tatri Dam. There are no detailed stability analyses or seepage analyses of the dam on record.

2.2 CONSTRUCTION

The dam was constructed by Mr. Kalicak, a contractor. Mr. Kalicak stated that the fill material was placed in less than 12-inch lifts and compacted with a sheepsfoot roller. The borrow area is now covered by water. There is no detailed information available.

2.3 OPERATION

No operating records exist. Outflow passes over an uncontrolled spillway.

2.4 EVALUATION

a. Availability. The only available engineering data are the personal recollections of the owner.

b. Adequacy. The field surveys and visual inspections presented herein are considered adequate to support the conclusions of this report. Seepage and stability analyses comparable to the requirements of the guidelines are not on record. This is a deficiency which should be rectified.

c. Validity. Not applicable.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. The owner accompanied the inspection team. Kal-Tatri is the downstream-most of a series of three lakes. The upper two lakes, Butterfly and Rainbow, were previously inspected and are evaluated in a separate report.

b. Project Geology. Outcrops found on both abutments and in the outlet channel are tan sandstone. The reservoir area is mapped as the Cambrian Bonne Terre formation. Thin residual soils consisting of brown clayey sand and sandy clay blanket bedrock in the reservoir area.

c. Dam. No detrimental settlement, cracking, sinkholes, sliding or significant erosion were observed in or near the embankment. Surface observations indicate the dam is constructed of brown clayey sand and sandy clay.

A typical embankment cross section is shown on PLATE 2. The 1V on 2.5H side slopes appear adequate for a dam of this height constructed from these materials. Tall weeds and light brush were present on the downstream slope. A number of small pine trees on the downstream slope had recently been cut and were laying on the slope. No large trees were present in the embankment except for one isolated group at the toe near the left abutment where the dam is very low.

The upstream slope of the dam had been covered with light brush but had recently been cleared. Cut brush was piled along the slope. Scattered sandstone boulders were present on the upstream face. Good engineering practice would be to provide adequately sized, graded riprap for wave protection; however, the very short fetch and hilly terrain around the lake minimize the likelihood of wave damage to the embankment.

No seepage was noted in or near the dam or abutments.

d. Appurtenant Structures. A concrete spillway is located on rock at the right abutment. The spillway consists of a vertical concrete wall with a notched weir. A partial concrete approach apron is provided upstream of the weir. The concrete was in good condition.

e. Reservoir Area. Some bank caving was noted immediately upstream of the spillway. This is not considered to be of any significance. No other pertinent problems were noted.

f. Downstream Channels. The spillway channel is composed of sandstone along the right face and invert, and soil and sandstone boulders to the left. In portions of the right face, soil is present under sandstone ledge rock and the face is being undercut somewhat. The outlet channel passes under a continuation of the dam road through three corrugated metal pipes in a concrete bridge-like structure. This structure allows overtopping of the road at large spillway flows.

3.2 EVALUATION

Brush and scattered small trees on the embankment are a potential seepage hazard and a potential habitat for burrowing animals. The practice of cutting the trees and brush should be continued. The boulders on the left bank of the outlet channel provide inadequate erosion protection for the adjacent earth embankment material and the erosion resistance of the embankment at this location for sustained high flows cannot be assured.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

Operational procedures are nonexistent since the dam has an uncontrolled spillway.

4.2 MAINTENANCE OF DAM

An effort at maintenance is evident by the cutting of trees and brush on the slopes, absence of large trees or erosion, etc. With mowing and removal of brush on the slopes, maintenance would be considered good.

4.3 MAINTENANCE OF OPERATING FACILITIES

Not applicable.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

No warning system is known to exist.

4.5 EVALUATION

Additional maintenance in the form of mowing and clearing brush from the embankments is recommended.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data. No design data were available.

b. Experience Data. The drainage area and lake surface area were developed from USGS Sprott and South West Weingarten, Missouri, 7-1/2 Minute Quadrangle Maps. The spillway was surveyed during the inspection.

c. Visual Observations.

(1) No drawdown facilities are available to evacuate the pool.

(2) There are no low level outlets.

(3) The spillway is located on the right abutment of the dam. The spillway consists of a weir located in a concrete wall. On the right side of the channel is a rock face. (See photographs 3, 6 and 7.) Flow over the weir will exit down a rocky channel. The spillway is judged to be sufficiently stable to pass overflows below the minimum elevation of the earth embankment, but erosion resistance of the left side of the outlet channel against sustained flows cannot be assured.

(4) Located downstream of the dam is a small concrete bridge with three 27-inch corrugated metal pipes. The bridge had no rails and appeared to be constructed as an overflow bridge. The bridge will have no hydraulic effect on the performance of the spillway. (See photographs 2, 3, and 7.)

d. Overtopping Potential. Lake Kal-Tatri will be overtopped by any flood greater than 5 percent of the Probable Maximum Flood (PMF). The guidelines require that a dam of this hazard potential (high) and size pass one-half PMF to the PMF without overtopping the dam. The two upstream dams, Butterfly and Rainbow, will pass 20 percent and 15 percent, respectively, of the PMF without overtopping the dam. Since Kal-Tatri will pass only 5 percent of the PMF without overtopping, it is probable that Kal-Tatri will be the first of the three dams to be overtopped. The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The maximum discharge for 50 percent of the PMF is 11,900 cfs. The maximum depth of flow over the minimum elevation of the earth embankment for 50 percent of the PMF is 6.0 feet. The duration of overtopping over the minimum elevation of the earth embankment for 50 percent of the PMF is 13 hours. Lake Kal-Tatri will not pass a 1 percent chance

flood without overtopping. A 1 percent chance flood is a flood with a 1 percent chance of being exceeded in any given year.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations. Visual observations of the dam and spillway are discussed and evaluated in Sections 3 and 5.
- b. Design and Construction Data. These data are discussed in Section 2. Original data on the dam are not known to exist. Seepage and stability analyses comparable to the requirements of the guidelines are not on record. This is a deficiency which should be rectified.
- c. Operating Records. No operating records exist.
- d. Post-Construction Changes. According to the owner, no post-construction changes have occurred.
- e. Seismic Stability. Kal-Tatri Dam is in seismic zone 2, for which the recommended guidelines assign a "moderate" damage probability. The relatively low height and clayey embankment material minimize the likelihood of failure due to earthquake shock.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety. The dam appears to be in generally good condition. Lack of adequate erosion protection on the left side of the spillway outlet channel, light brush on the dam slopes, and insufficient spillway capacity to pass the Probable Maximum Flood without overtopping the dam are deficiencies which should be corrected.

b. Adequacy of Information. Conclusions herein are based on discussion with the owner-builder, visual inspection, and field surveys. Seepage and stability analyses are not on record as recommended in the guidelines. This is a deficiency which should be corrected.

c. Urgency. We recommend the remedial measures listed in Section 7.2 be accomplished in the near future. The item recommended in paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II. No Phase II inspection is recommended. The recommended remedial actions can be accomplished without further investigation.

7.2 REMEDIAL MEASURES

The following remedial measures are recommended:

a. Spillway capacity and/or height of the dam should be increased to pass the PMF without overtopping the dam.

b. Provide better erosion protection at the dam/spillway interface left side of the outlet channel to prevent erosion due to high spillway flows.

c. Remove brush on dam slopes.

d. The dam should be periodically inspected and evaluated by an engineer experienced in the design and construction of earth dams. Records should be kept of these inspections and major maintenance.

e. Stability and seepage analyses should be performed by a professional engineer experienced in the design and construction of dams.






PLATE I





LAKE KAL-TATRI
PROFILE



No. 1 UPSTREAM FACE




NO. 2 DOWNSTREAM BRIDGE AND CULVERTS



NO. 3 SPILLWAY AND OUTLET CHANNEL




NO. 4 DOWNSTREAM BRIDGE AND CULVERTS



NO. 5 DOWNSTREAM SLOPE



NO. 6 SPILLWAY



NO. 7 SPILLWAY

APPENDIX A

HYDROLOGIC AND HYDRAULIC ANALYSIS METHODOLOGY

HYDROLOGIC AND HYDRAULIC ANALYSIS OF OVERTOPPING

1. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33." Reduction factors have not been applied. A 24-hour storm duration is assumed with the total rainfall depth distributed over 5-hour periods in accordance with procedures outlined in FM 1119-2-1411 (SPE Determination). The maximum 6-hour rainfall period is then distributed to hourly increments by the same criteria. Within the hour distribution is based upon NOAA Technical Memorandum NOS HYDRO 35. The non peak 6-hour rainfall periods are distributed on a daily basis. All distributed values are arranged in a critical sequence by the SCS criteria. The final inflow hydrograph is produced by determining the infiltration losses appropriate to each day, hour, and minute for meteorologic conditions.

2. The reservoir routing is accomplished by using the 2.1 routing techniques which include the routing of the inflow hydrograph through lake storage. Hydraulic computations are performed for the routing and crest of dam is computed as a function of the inflow hydrograph. Storage in the reservoir is determined as a function of the inflow curve. The hydraulic capacity of the reservoir is determined and the top of dam is defined by observed data for the reservoir.

3. Dam overtopping analysis has been completed by using the methods for this dam and lake. The results are presented as a percentage of the PMF hydrograph that the reservoir can store without the dam being overtopped. The output generated by the hydrologic appendice explains the basis of the analysis and the characteristics of the simulated hydrograph.

4. The above methodology has been modeled and run in this report using the systemized computer program HEC-1 (Hydrologic Engineering Center, July 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California). The specific parameters estimated for this site are listed in the attached computer printout. Definitions of these variables are contained in the "User's Manual" for the computer program.

[illegible]

47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63

1

P 0 26 100 120 130
T
W2 -10 .031
X -10 .031
K 2 RAINBOW AND 3.0
K1 KAL-TATHI LAKES 0
K 1 KAL-TATHI LAKES 0
K1 MESERVOIR ROUTING OF RAINBOW AND KAL-TATHI 0
Y 1
V1 1
V4742.95 744.0 745.19 746 747 748 748 750 751 752 753
V5 0 88 331 545 903 1635 5989 10181 15049 22687
SA 0 10 18
SE 725 743 763
33742.95
30745.14
K

-1 -89 0 .18

COMBINED

SUB-AREA RUNOFF COMPUTATION

SUBAREA RUNOFF FOR LAKE KAL-TATHI
ISTAG ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
6 0 0 0 0 0 1 0 0

IMYDG IUNG TAKEA SNAP TRSDA TRSPC RATIO ISNOW ISAME LOCAL
1 2 .09 0.00 .09 1.00 0.000 0 0 0

PRECIP DATA
SPFE PMS R6 R12 R24 R48 R72 R96
0.00 26.00 100.00 120.00 130.00 0.00 0.00 0.00 0.00

LOSS DATA
LROPT STRR DLIRR RTIOL ERRAIN STRKS RTIOK STRIL CNSTL ALSMX RIIMP
0 0.00 0.00 1.00 0.00 0.00 0.00 1.00 -1.00 -89.00 0.00 .18

CURVE NO = -89.00 WETNESS = -1.00 EFFECT CN = 89.00

UNIT HYDROGRAPH DATA
TC= 0.00 LAG= .03

RECESSION DATA
STRTO= -10.00 QNCSN= -.10 RTIOR= 3.00

TIME INCREMENT TOO LARGE--(NMU IS GT LAG/2)

UNIT HYDROGRAPH 5 END OF PERIOD ORIGINATES, TC= 0.00 HOURS, LAG= .03 VOL= 1.00
518. 145. 26. 0.

FLows IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				.01	.05	.10	.15	.20	.30	.40	.50	1.00
RATIOS APPLIED TO FLOWS												
HYDROGRAPH AT 1												
	(1.83	(186.	929.	1858.	2787.	3715.	5573.	7431.	9289.	10577.
	(4.74)	(5.26)	26.30)	52.60)	78.91)	105.21)	157.81)	210.42)	263.02)	526.05)
ROUTED TO 2												
	(1.83	(57.	159.	371.	917.	1500.	2987.	4841.	6976.	15035.
	(4.74)	(1.62)	4.49)	10.51)	25.96)	42.48)	84.59)	137.07)	197.53)	451.23)
HYDROGRAPH AT 3												
	(.89	(95.	474.	948.	1421.	1895.	2843.	3790.	4738.	9475.
	(2.31)	(2.68)	13.42)	26.83)	40.25)	53.66)	80.49)	107.32)	134.15)	268.31)
2 COMBINED												
	(2.72	(150.	568.	1174.	1680.	2933.	4784.	7387.	10620.	23738.
	(7.00)	(4.26)	16.09)	33.40)	53.39)	83.05)	135.46)	209.18)	300.72)	672.18)
ROUTED TO 5												
	(2.72	(112.	249.	567.	1146.	1979.	4354.	6490.	12762.	23484.
	(7.00)	(3.74)	7.05)	16.07)	32.46)	56.03)	123.28)	197.93)	361.34)	659.36)
HYDROGRAPH AT 6												
	(.09	(17.	85.	169.	254.	339.	508.	677.	847.	1694.
	(.23)	(.48)	2.40)	4.80)	7.19)	9.59)	14.39)	19.18)	23.96)	47.96)
2 COMBINED												
	(2.81	(146.	258.	587.	1178.	2021.	4422.	7091.	12420.	23599.
	(7.26)	(4.19)	7.31)	16.63)	33.36)	57.23)	125.22)	200.70)	365.86)	668.26)
ROUTED TO 8												
	(2.81	(137.	253.	577.	1169.	2015.	4376.	7095.	10958.	23313.
	(7.26)	(3.68)	7.17)	16.34)	33.09)	57.06)	123.92)	200.89)	310.31)	660.14)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION	INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
	STORAGE	803.50	803.50	808.00
	OUTFLOW	1442.	1442.	1768.
		55.	55.	1975.

RATIO OF PHF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.01	803.57	0.00	1447.	57.	0.00	16.42	0.00
.05	804.59	0.00	1518.	159.	0.00	18.08	0.00
.10	805.79	0.00	1604.	371.	0.00	17.33	0.00
.15	806.85	0.00	1667.	917.	0.00	16.33	0.00
.20	807.39	0.00	1722.	1500.	0.00	16.25	0.00
.30	808.43	.43	1801.	2987.	.83	16.08	0.00
.40	809.12	1.12	1854.	4641.	1.50	16.00	0.00
.50	809.60	1.60	1991.	6976.	2.25	16.00	0.00
1.00	811.14	3.14	2014.	15935.	5.58	15.92	0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION INITIAL VALUE SPILLWAY CREST TOP OF DAM
767.70 767.70 771.40

STORAGE
OUTFLOW

343.
131.

343.
131.

471.
1644.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.01	767.71	0.00	343.	132.	0.00	15.92	0.00
.05	768.33	0.00	364.	249.	0.00	17.33	0.00
.10	769.45	0.00	403.	567.	0.00	17.17	0.00
.15	770.79	0.00	450.	1148.	0.00	16.92	0.00
.20	771.74	.34	483.	1978.	1.42	16.42	0.00
.30	772.62	1.42	522.	4354.	3.08	16.08	0.00
.40	773.56	2.16	549.	6900.	4.33	16.08	0.00
.50	774.07	2.67	568.	12762.	5.33	15.92	0.00
1.00	775.50	4.10	621.	23284.	7.42	15.92	0.00

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION INITIAL VALUE SPILLWAY CREST TOP OF DAM
742.95 742.95 745.19

STORAGE
OUTFLOW

60.
0.

60.
0.

83.
331.

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.01	744.24	0.00	73.	137.	0.00	15.75	0.00
.05	744.81	0.00	79.	253.	0.00	16.08	0.00
.10	746.09	.90	93.	577.	5.83	17.67	0.00
.15	747.36	2.17	107.	1169.	8.23	17.17	0.00
.20	748.17	2.98	116.	2015.	9.92	16.50	0.00
.30	749.26	4.07	130.	4376.	11.25	16.17	0.00
.40	750.26	5.07	142.	7095.	12.50	16.08	0.00
.50	751.24	5.95	151.	10958.	13.83	15.92	0.00
1.00	753.10	7.91	179.	25313.	16.00	15.92	0.00